
A
117°13′W
117°10′W
37°34′N
37°32′N
Spectral
Alteration Zones
N
Direction of view in (B)
95
Cuprite Hills Fault
Western Center
Eastern Center
Prospect
Fault Zone
A
A′
1
2
Advanced
argillic
Hydrated
silica
Alunite
Argillic
Kaolinite
White mica ±
montmorillonite
Adularia-
smectite
Buddingtonite
± smectite
Propylitic
Chlorite
Unaltered
DC
resistivity
sounding
U
D
0
2 Km

B


Western
Center
Unaltered
Phyllite
Hydrated
Silica
Prospect Fault
Zone
Advanced
argillic
alteration
Cuprite Hills
Fault
North
U
D